


Proposed Revisions to the Figures



Red lines indicate that the revised drawings now have the correct hatching.

This comment applies throughout the rest of the figures.




Fig. 1B





FIG. 2A



Section A-A
FIG. 2B




Fig. 3




FIG. 4




FIG. 5




FIG. 6





FIG. 7A



Section A-A

FIG. 7B




FIG. 8A




FIG. 8B




FIG. 8C




FIG. 9A




FIG. 9B




FIG. 9C




FIG. 9D




FIG. 9E




Fig. 10





Fig. 11A



Section A-A

Fig. 11B




Fig. 12

[illegible]

FIG. 1 is a schematic diagram of a square frame assembly. The assembly includes a central white square (101) surrounded by a thick, hatched border (108). Four circular fasteners (105) are positioned at the corners of the hatched border, securing it to a base.

FIG. 1B



2/12





FIG. 2A



Section A-A

FIG. 2B



3/12




FIG. 3

4/12




FIG. 4



5/12




FIG. 5



6/12




FIG. 6

DiBene II, et al.
Appl.: 09/801, 437 Atty. Docket: INCEP.007A

7/12





FIG. 7A



Section A-A

FIG. 7B



8/12




FIG. 8A




FIG. 8B




FIG. 8C



9/12




FIG. 9A




FIG. 9B




FIG. 9C




FIG. 9D




FIG. 9E




FIG. 10



11/12





FIG. 11A



Section A-A

FIG. 11B



12/12




FIG. 12